

Technical Masterclass: Graphite Electrodes in Steelmaking

Manufacturing Technologies, Classifications, Applications, Consumption Optimization & Breakage Fractography

Prepared and Delivered by: Consultant Eng. Emad El-Masry (Norafrika Metals)

Location: Delivered at Ezz Steel Facilities

1. Introduction & Operational Role

Graphite electrodes serve as the vital conductive conduit for electric power transmission and arc generation, melting heavy scrap, direct reduced iron (DRI), and alloys inside Electric Arc Furnaces (EAF) and Ladle Refining Furnaces (LF).

2. Main Classifications (RP / HP / UHP)

Graphite electrodes are classified based on their permissible current-carrying capacity, bulk density, and raw material composition:

- **RP (Regular Power):**
 - **Raw Material:** Regular petroleum coke.
 - **Allowable Current Density:** 14 – 18 A/cm²
 - **Primary Applications:** Small arc furnaces, silicon metal smelting, yellow phosphorus, and standard ferroalloys.
- **HP (High Power):**
 - **Raw Material:** Petroleum coke blended with approximately 30% needle coke.
 - **Allowable Current Density:** 18 – 24 A/Cm²
 - **Primary Applications:** Medium-power electric arc furnaces and Ladle Refining Furnaces (LF).
- **UHP (Ultra High Power):**
 - **Raw Material:** 100% premium needle coke.
 - **Allowable Current Density:** 24 – 32+ A/Cm²
 - **Primary Applications:** Modern high-productivity, high-capacity EAF steel melt shops.

3. Core Manufacturing Phases

1. **Crushing & Mixing:** Pulverizing premium needle/petroleum coke and intensive blending with coal tar pitch at temperatures exceeding 150°C.
2. **Extrusion:** Hydraulic hot extrusion forming dense green electrode cylinders to target diameters.

3. **Baking:** Carbonization up to 800–1,000°C in multi-chamber ring furnaces to carbonize the pitch binder into solid carbon matrix.
4. **Impregnation:** High-pressure liquid pitch autoclave impregnation to eliminate porosity and maximize mechanical density (repeated for HP/UHP grades).
5. **Re-baking:** Stabilizing impregnated pitch volatiles.
6. **Graphitization:** Direct electrical resistance heating up to 2,800–3,000°C (Acheson or LWG systems), ordering amorphous carbon into a hexagonal graphite crystalline lattice.
7. **Precision Machining:** CNC thread turning of electrode sockets and fabrication of connecting male nipples.

4. Comparative Technical Properties

- **Specific Electrical Resistivity:** Significantly reduced in UHP (4.5 – 5.5 $\mu\Omega\cdot\text{m}$) compared to RP (7.0 – 8.5 $\mu\Omega\cdot\text{m}$), minimizing resistive Joule heat losses under massive amperage.
- **Coefficient of Thermal Expansion (CTE):** Extremely low in UHP ($1.0 - 1.4 \times 10^{-6} / \text{K}$), offering superior thermal shock endurance during severe arc ignition.
- **Bulk Density:** Ranging from 1.58 g/cm^3 for RP up to 1.68 – 1.72+ g/cm^3 for UHP grades.

5. Joint Tightening Torque Specifications

Connecting nipples represent the most mechanically and electrically vulnerable section of the column.

Critical Safety Warning: Never apply conventional greases or oils to thread joints; these compounds carbonize under intense temperatures, creating severe electrical insulation, arcing, and catastrophic joint destruction.

Electrode Diameter (mm / inch)	Standard Nipple Type	Recommended Tightening Torque (N·m)
300 - 350 mm (12" - 14")	Male-Female / Nipple 4 TPI	700 – 900
400 - 450 mm (16" - 18")	Male-Female / Nipple 4 TPI	1,100 – 1,400
500 - 550 mm (20" - 22")	Nipple 3 TPI / 4 TPI	1,800 – 2,400

Electrode Diameter (mm / inch)	Standard Nipple Type	Recommended Tightening Torque (N·m)
600 mm (24")	Nipple 3 TPI / 4 TPI	2,500 – 3,200
700 - 750 mm (28" - 30")	Nipple 3 TPI (UHP EAF)	3,500 – 4,500

Note: Undertorquing causes air gaps, micro-arcing, and sheared nipples; overtorquing induces hoop stresses that rupture electrode socket walls.

6. Step-by-Step Joint Connection Procedure

1. **Cleaning:** Thoroughly blow-clean socket and nipple threads using dry, oil-free compressed air.
2. **Vertical Alignment:** Hoist the new electrode utilizing a flexible hoisting plug to guarantee absolute coaxial alignment.
3. **Manual Engagement:** Thread down smoothly until faces make uniform preliminary contact.
4. **Final Torquing:** Apply torque in a single smooth motion using a calibrated torque wrench until preset torque is reached, confirming zero clearance with a 0.05 mm feeler gauge.

7. Fracture Fractography & Root-Cause Failure Analysis

- **Bending / Transverse Fracture:** Flat transverse surface displaying a compression lip on one perimeter edge; caused by heavy scrap cave-ins, non-conductive boring into lime, or mast vibration.
- **Sheared Nipple:** Complete shearing across the nipple core; caused by undertorquing, transferring all bending loads to the nipple rather than the outer column faces.
- **Socket Splitting:** Longitudinal vertical rupture running through the socket wall; caused by excessive overtorquing combined with thermal expansion.
- **Electrical Arcing Breakage:** Eroded, glazed, or burned cone threads; caused by joint loosening generating continuous internal micro-arcing.
- **Thermal Shock Spalling:** Cup-and-cone detachment at the lower tip; caused by high current inrushes on cold electrodes or out-of-spec CTE.

8. Scrap Layering Profile (Bottom to Top)

- **1. Bottom:** Clean light scrap, turnings, and carbon/lime additions (protects hearth refractory and forms early molten heel).

- **2. Lower-Middle:** Heavy melt, thick plates, bundles, and skull (safely positioned below initial boring stroke).
- **3. Upper-Middle:** Medium structural and plate scrap (stabilizes the burden and cushions heavy melts).
- **4. Top:** Clean, light shredded busheling scrap (ensures fast ignition and smooth boring-in without tip damage).

9. Specific Consumption Benchmarks & Optimization

Specific Electrode Consumption Kg/t = Total Consumed Electrodes Kg / Total Prime Liquid Steel t

- **Modern UHP AC EAF:** 1.0 – 1.6 Kg/t
- **Standard AC EAF:** 1.8 – 2.8 Kg/t
- **DC Single-Electrode EAF:** 0.8 – 1.2 Kg/t
- **Ladle Refining Furnace (LF):** 0.25 – 0.45 Kg/t

Operational Savings Matrix:

- Water spray cooling rings maintenance: **10 – 15% reduction**
- Dense, consistent foamy slag practice: **6 – 10% reduction**
- Tap-to-tap cycle reduction by 5 minutes: **4 – 7% reduction**
- Standardized torquing and cave-in prevention: **5 – 12% reduction**